Before the Federal Communications Commission Washington, D.C. 20554

In the Matter of)	
Techcore Consultants II Inc.)	File No. EB-11-PO-0093
Physical System ID # 007506)	
Community ID # OR0055)	
)	NOV No. V201132920028
Enterprise, Oregon	j	

NOTICE OF VIOLATION

Released: August 31, 2011

By the Resident Agent, Portland Resident Agent Office, Western Region, Enforcement Bureau:

- 1. This is a Notice of Violation ("Notice") issued pursuant to Section 1.89 of the Commission's Rules, to the Techcore Consultants II Inc. ("Techcore"), operator of a cable system in Enterprise, Oregon.
- 2. On August 11, 2011, an agent of the Enforcement Bureau's Portland Resident Agent Office inspected the Techcore's cable system located in Enterprise, Oregon, and observed the following violation:
 - a. 47 C.F.R. § 76.605(a)(12): "As an exception to the general provision requiring measurements to be made at subscriber terminals, and without regard to the type of signals carried by the cable television system, signal leakage from a cable television system shall be measured in accordance with the procedures outlined in § 76.609(h) and shall be limited as follows: Over 54 MHz up to and including 216 MHz 20 micro-volts per meter, measured at 3 meters." At the time of the inspection, the agent observed signal leakage in excess of 20 micro-volts per meter on the frequency 127.2625 MHz at the following locations:
 - 1) Corner of West Greenwood Street and South Depot Street: 166 µV/m
 - 2) Corner of South Depot Street and SW Boyd Court: 175 µV/m
 - 3) Corner of SW 2^{nd} and Litch Street: $\,175\;\mu V/m$

_

¹ 47 C.F.R. § 1.89.

3. Pursuant to Section 403 of the Communications Act of 1934, as amended, and Section 1.89 of the Commission's Rules, Techcore, must submit a written statement concerning this matter within 20 days of release of this Notice. The response must fully explain each violation, must contain a statement of the specific action(s) taken to correct each violation and preclude recurrence, and should include a time line for completion of pending corrective action(s). The response must be complete in itself and signed by a principal or officer of the Techcore. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

Federal Communications Commission Portland Resident Agent Office POB 61469 Vancouver, WA 98666-1469

- 4. This Notice shall be sent to Techcore Consultants II Inc. at its address of record.
- 5. The Privacy Act of 1974³ requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance. Any false statement made knowingly and willfully in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.⁴

FEDERAL COMMUNICATIONS COMMISSION

Binh Nguyen Resident Agent Portland Resident Agent Office Western Region Enforcement Bureau

² 47 U.S.C. § 403.

³ P.L. 93-579, 5 U.S.C. § 552a(e)(3).

⁴ 18 U.S.C. § 1001 et seq.